

Bāng

CARE SHEET

ĐIEM[?] Collection

Powder coated steel

Test Before Cleaning

Always test a small, hidden part of the product (e.g., the back) before cleaning to check for any issues.

Dust and Fingerprints

Use a clean, dry soft cloth to remove dust and fingerprints.

Persistent Issues

If needed, use a soft damp cloth with warm water and dishwashing liquid.

Dry After Cleaning

Always dry the surface with a dry cloth to avoid cleaning marks.

Avoid Abrasives

Never use powdered abrasives, cleaning solutions with abrasives, or scouring pads, as these can damage the surface.

Varnished raw metal

Test Before Cleaning

Always test a small, hidden part of the product (e.g., the back) before cleaning to check for any issues.

Dust and Fingerprints

Use a clean, dry soft cloth to remove dust and fingerprints.

Persistent Issues

If needed, use a soft damp cloth with warm water and dishwashing liquid.

Dry After Cleaning

Always dry the surface with a dry cloth to avoid cleaning marks.

Avoid Abrasives

Never use powdered abrasives, cleaning solutions with abrasives, or scouring pads, as these can damage the surface.

Glass table top

Dust and Fingerprints

Use a clean, dry soft cloth to remove dust and fingerprints.

Persistent Issues

If needed, use a soft damp cloth with warm water and dishwashing liquid.

Dry After Cleaning

Always dry the surface with a dry cloth to avoid cleaning marks.

Avoid Abrasives

Never use powdered abrasives, cleaning solutions with abrasives, or scouring pads, as these can damage the surface.

CARE SHEET

LÓP Collection

Opal glass

Dust and Fingerprints

Use a clean, dry soft cloth to remove dust and fingerprints.

Avoid Abrasives

Never use powdered abrasives, cleaning solutions with abrasives, or scouring pads, as these can damage the surface.

Casted acrylic

Test Before Cleaning

Always test a small, hidden part of the product (e.g., the back) before cleaning to check for any issues.

Dust and Fingerprints

Use a clean, dry soft cloth to clean dust and fingerprints using a circular motion.

Persistent Issues

If needed, use a soft damp cloth with warm water and dishwashing liquid.

Dry After Cleaning

Always dry the surface with a dry cloth after cleaning

Avoid Abrasives

Never use powdered abrasives, cleaning solutions with abrasives, or scouring pads, as these can damage the surface.

Avoid Direct Sunlight

Colored acrylic will fade over time when exposed to direct sunlight due to ultraviolet radiation. Avoid direct sunlight when possible.

CARE SHEET

**UNBORING
OBJECTS**

Bübing